



Cut trace here

Solder jumper here