




Sweep	Trace	Color	Line Style	Thick	Data	Axis	Comment
1	1	Red	Solid	1	Anlr.Level A	Left	
1	2	Magenta	Solid	1	Anlr.TH+D+N Ratio	Right	
1	3	Yellow	Solid	1	Anlr.Level B	Left	
1	4	Red	Solid	1	Anlr.TH+D+N Ratio	Right	




Sweep	Trace	Color	Line Style	Thick	Data	Axis	Comment
1	1	Red	Solid	1	Anlr.Level A	Left	
1	2	Magenta	Solid	1	Anlr.THd+N Ratio	Right	
1	3	Yellow	Solid	1	Anlr.Level B	Left	
1	4	Red	Solid	1	Anlr.THd+N Ratio	Right	



Sweep	Trace	Color	Line Style	Thick	Data	Axis	Comment
1	1	Red	Solid	1	Anlr.Level A	Left	
1	2	Magenta	Solid	1	Anlr.TH+N Ratio	Right	
1	3	Yellow	Solid	1	Anlr.Level B	Left	
1	4	Red	Solid	1	Anlr.TH+N Ratio	Right	



Sweep	Trace	Color	Line Style	Thick	Data	Axis	Comment
1	1	Red	Solid	1	Anlr.Level A	Left	
1	2	Magenta	Solid	1	Anlr.TH+D+N Ratio	Right	
1	3	Yellow	Solid	1	Anlr.Level B	Left	
1	4	Red	Solid	1	Anlr.TH+D+N Ratio	Right	



Sweep	Trace	Color	Line Style	Thick	Data	Axis	Comment
1	1	Red	Solid	1	Anlr.Level A	Left	
1	2	Magenta	Solid	1	Anlr.TH+D+N Ratio	Right	
1	3	Yellow	Solid	1	Anlr.Level B	Left	
1	4	Red	Solid	1	Anlr.TH+D+N Ratio	Right	